Date	2212Z 11 J A	IN 1961	37.005 w	CH/OPS DR W	B DB	FOUT AU PIC
	DIRECTOR 25X1 DPD (1-2-3-4-5-6-7-8-9-1		8-9-10	PROUD PROUD AIR SULPAN CONTROL	PRIORITY	
INFO	*S/C (11) CLZ TOR: 2237Z		069	INITIAL WHEN READ ACTION CY. TO:	25X1	IN-42279
To	OP IMFOR	25X1 WARDS FO	EFO	25X1 CAMERA OPERATION	RE PORT RE M	ission 3024

- MATERIAL RECEIVED.
- 2. EXPOSURE NBR 1415 R 1 L WAS BLURRED. (PROBABLE SHUTTER MALFUNCTION).
- 3. THREE FACTORY SPLICES WERE FOUND ON THE "R" ROLL.
- 4. APPROX 200 FRAMES HAVE CREASES WHICH OCCURRED DURING FILM PROCESSING.
- 5. PROCESSING DATA.

DEVELOPER D-19 REPLENISHER D-19

250 CC/MIN

PROCESSING SPEED 5 FT/MIN 68 DEGREES

GAMMA LOW 2.04, HIGH 2.14.

END OF MESSAGE

DOPTIONET NO. THE CLASS.	
CONTRACTOR OF THE OR	25X1
Dan 18 Supt 86 -	ALT BU ANALYST NAME (ANALYST ON CONTROL OF C
	TOPSECRET
REPRODUCTION BY OTI	HER THEN THE SRANG OFFICE IS PROHIBITED.

Copy No.